

Oil Field Environmental Incident Summary

Incident: 20170306123800 **Date/Time of Notice:** 03/06/2017 12:38

Responsible Party: Caliber Midstream North Dakota LLC

Well Operator: CALIBER MIDSTREAM NORTH DAKOTA LLC

Well Name: DAPL Watford Terminal

Field Name:

Well File #:

Date Incident: 3/3/2017

Time Incident: 00:45

Facility ID Number:

County: MCKENZIE

Twp: 149

Rng: 99

Sec: 1

Qtr:

Location Description:

Submitted By: Jason Fox

Received By:

Contact Person: Skip Vest
13811 24th St. NW
Alexander, ND 58831

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2000 Feet

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Spill was contained.

Potential Environmental Impacts:

Soil contamination in immediate spill area. Soil was removed during clean up.

Action Taken or Planned:

When the spill of approximately 2 barrels occurred, the pipeline was immediately isolated, stopping flow. The stainless tubing was re-inserted into the compression fitting and tightened. The bolts on the leaking 12" flange were re-torqued to manufacturer's specification using a calibrated torque wrench. Spill was contained on level ground within the facility's fence. A spill response contractor was contacted and responded to remove the spilled waste with a vacuum truck. The majority of the area affected was only covered with a mist that settled on top of the snow, without penetrating to the ground. All of the contaminated snow was vacuumed into the vacuum truck. The only pooling was under the source of the leak which covered an approximate area of 10' X 20'. This area had the snow and contaminated soil removed by the vacuum truck. No personnel, wild life, or waterways were negatively impacted.

Wastes Disposal Location: Secure Energy 13 Mile Special Waste Landfill

Agencies Involved:

Updates

Date: 3/6/2017 ***Status:*** Inspection

Author: Torgerson, Brad

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 3/6/2017 at 6:00 pm - Mostly Cloudy, Windy and 19 Degrees F. Met with Jason Fox of Caliber Midstream North Dakota LLC at the DAPL Watford City Terminal. Mr. Fox showed me the location of the leak area. According to Mr. Fox, Secure Energy Services vacuumed-up the crude oil impacted snow and soil and transported it to the Secure Energy Services 13 Mile Facility. The release impacted area appeared to be appropriately cleaned-up. No further follow-up appears to be necessary.